

CENTURY MINE STREAM MITIGATION PHOTOGRAPHS
Piney Creek



Photograph: 42
PCNL-1: Successful stream bank planting area



Photograph: 43
PCNL-2: Steep Bank Restoration Incomplete



Photograph: 44
PCNL-2: Log vane missing J-hook



Photograph: 45
PCNR-2 Unsuccessful stream bank restoration



Photograph: 46
PCNR-2 Unsuccessful stream bank restoration



Photograph: 47
PCSL-1 : Partially Successful lower bank restoration